

ReDIP INDICATOR

ReDip indicator takes the guesswork out of shell drying. For use with water-based binders, the color indicator prevents loss due to sloughing of undried coats, reduces time spent overdrying shells and allows the caster to produce stronger shells by ensuring that each coat is fully dried before applying an additional coat.

ReDip indicator's unique composition tells you exactly when the moisture is out of the shell with a simple, visible color change. With ReDip indicator, wet shells are greenish-yellow in color, dry shells are orange. During firing, the indicator is burned off and the shell returns to its normal color.



ReDip indicator is inert and will not affect the slurry or shell in any way. ReDip indicator is non-toxic and non-hazardous.

Application Recommendations

Use 1 to 1.5 parts ReDip indicator to 200 parts binder, by volume, in your slurry for drying control with color.

As the conditions or methods of use are beyond our control, we do not assume any responsibility and expressly disclaim any liability for any use of this product. Information contained herein is believed to be true and accurate but all statements or suggestions are made without warranty, expressed or implied, regarding accuracy of the information, the hazards connected with the use of the material or the results to be obtained from the use thereof. Compliance with all applicable federal, state, and local regulations remains the responsibility of the user. All potential liability related to the sale and use of this product is limited to the cost of the particular goods sold in their respective transactions.



RANSOM & RANDOLPH

3535 Briarfield Boulevard | Maumee, OH 43537 USA
800.800.7496 | 419.865.9497 | 419.865.9997 (FAX) | www.ransom-randolph.com



Issue Date: July 26, 2023

Investing with Innovation™